## पेटेंट कार्यालय शासकीय जर्नल

# OFFICIAL JOURNAL OF THE PATENT OFFICE

निर्गमन सं. 18/2022 ISSUE NO. 18/2022

शुक्रवार FRIDAY दिनांकः 06/05/2022

DATE: 06/05/2022

## पेटेंट कार्यालय का एक प्रकाशन PUBLICATION OF THE PATENT OFFICE

(19) INDIA

(51) International

(86) International

(87) International

**Publication No** 

Filing Date

Filing Date

**Application Number** 

Filing Date

(62) Divisional to

(61) Patent of Addition:NA

to Application Number :NA

Application No

classification

(22) Date of filing of Application :30/04/2022

:A61C0008000000, G16H0015000000,

G01N0029110000, A61L0027060000,

H01B0007280000

:NA

:NA

: NA

:NA

:NA

(43) Publication Date: 06/05/2022

#### (54) Title of the invention: MICROGRAPHIC INVESTIGATION OF EXPLANTED METALLIC BIOMEDICAL IMPLANTS FOR CORROSION, OTHER MECHANICAL DAMAGE RESPONSIBLE FOR FAILURE

(71)Name of Applicant:

1)Dr. Vaibhay Trivedi

Address of Applicant : Professor, Mechanical Engineering Department, IFTM University, Moradabad, Uttar Pradesh -

244102 -----Name of Applicant: NA

Address of Applicant: NA (72) Name of Inventor:

1)Mr. Mohammad Javed

Address of Applicant : Assistant Professor, Mechanical Engineering Department, IFTM University, Moradabad, Uttar

Pradesh - 244102 -----

2)Mr. Mayank Bharadwaj

Address of Applicant : Assistant Professor, Mechanical Engineering Department, IFTM University, Moradabad, Uttar

Pradesh - 244102 -----

3)Mr. Kuldeep Dubey

Address of Applicant : Assistant Professor, Mechanical Engineering Department, IFTM University, Moradabad, Uttar

Pradesh - 244102 -----

4)Mr. Prashant Kumar

Address of Applicant : Assistant Professor, Mechanical Engineering Department, IFTM University, Moradabad, Uttar

Pradesh - 244102 -----

5)Mr. Vivek Shankhdhar

Address of Applicant : Assistant Professor, Mechanical Engineering Department, IFTM University, Moradabad, Uttar

Pradesh - 244102 -----

### (57) Abstract:

The present invention relates to with detailed corrosion analysis of explanted devices. The study of total 6 different types of orthopedic metallic implant was carried out after collecting the clinical report from the doctors, who performed these implantations. The clinical report covered the purpose of im-plantation, body part where implantation was done, and physiological reasons of removal of im-plant. The metallurgical investigation to study corrosion and any other mechanical damage to the implant surface during their service period was done using the Scanning Electron Micrography. SEM presented in this paper reveals the presence of in-vitro corrosion and mechanical damage as well, which are corroborating well with clinical reports.

No. of Pages: 17 No. of Claims: 2